

Flood Report Att 5 Schedule of Maintenance

ATTACHMENT 5

Schedule of Maintenance & Upgrade Actions

Suburb	Street	Action
Cooroy	Ashgrove Drive	Proposed improvements for routine scheduled maintenance to the inlet and outlet of Ashgrove Drive culvert.
Cooroy	Ashgrove Drive	Determine if improved hydraulic efficiency can be achieved at the inlet to the 3/600 culvert under Ashgrove.
Cooroy	Oak Street	Proposed improvements for routine scheduled maintenance to the table drain on the eastern side of Oak and the receiving channel in Oak Bushland Reserve.
Cooroy	Oak Street	Determine if improved hydraulic efficiency can be achieved at the downstream end of Oak (headwall assessment)
Cooroy	Various	Survey of original assessment area in preparation for a complete 2D hydraulic model. Also including collaboration with DTMR studies involved with the Bruce Highway upgrade.
Pomona	Reserve/Rifle Street	Modifications at the culvert and footbridge location. As well as Rifle Street longitudinal drainage improvements.
Pomona	Rifle Street	Proposed improvements for routine scheduled maintenance to the open drain.
Pomona	Station Street	Proposed improvements for routine scheduled maintenance of the culvert outlet.
Pomona	Various	Survey of original assessment area in preparation for a complete 2D hydraulic model.
Pomona	Exhibition Street	Determine if improved hydraulic efficiency can be achieved at the bridge.
Pomona	Mill Street	Determine if improved hydraulic efficiency can be achieved at the culverts.
Pomona	Station Street	Determine if improved hydraulic efficiency can be achieved at the subway crossing.
Tewantin	Golf Course Drive	Proposed improvements for routine scheduled maintenance to the inlet and outlet of Golf Course Drive culvert.
Tewantin	Golf Course Drive/Mckinnon Drive	Pending survey results approach the Department of Environment & Heritage Protection to investigate the likelihood of permanent access rights for regular maintenance within conservation land.
Tewantin	Daintree Way/Homestead Drive/Leafhaven Drive	Proposed improved maintenance of the internal Daintree Estate drain (between Homestead & Leafhaven Drive) and Daintree Way culvert.
Alexandra Heads	Various	Inspection and potential rehabilitation of underground pipe joint displacements
Alexandra Heads	Janet Street	Potential implementation of concept design.
Buddina	Beltana Crescent	Overland flow path establishment. Potential open drain construction.
Buddina/ Minyama	Various	Inspection and potential rehabilitation of underground pipe joint displacements
Maroochydore/ Mooloolaba	Various	Inspection and potential rehabilitation of underground pipe joint displacements

Note: Identification of revised maintenance regimes and upgrade actions for the regions including Alexandra Headlands, Buddina, Minyama, Maroochydore and Mooloolaba are ongoing. Establishment is anticipated through the draft report recommendations.