

Flood Report Att 4 Actions

ATTACHMENT 4

Actions Taken To Date

Suburb	Street	Action
Cooran	King Street	Terrain reshaped next to shop buildings to promote overland flow.
Cooroy	Ashgrove Drive/Oak Street	Slab level survey undertaken of homes not yet checked against the Australian Height Datum (AHD).
Cooroy	Oak Street	Silt and weed removal from table drain at cul-de-sac.
Cooroy	Oak Street	Silt and weed removal at stormwater outlet near Garnet street intersection. Including erosion and bank stabilisation at the inlet.
Cooroy	Ashgrove Drive	Silt and debris removal at the stormwater inlet between properties 23 and 25.
Cooroy	Ashgrove Drive	Silt, weed and outlet grate removals at the stormwater outlet between properties 20 and 22.
Cooroy	Lawville Road	Debris cleared from table drain.
Cooroy	Ponderosa Drive	Collection of storm damaged vegetation and foreign material.
Federal	Middle Creek Road	Works undertaken to establish existing table drain.
Kin Kin	Main Street	Clearing of underground pipe.
Lake Macdonald	Forest Acres Drive	Table drain clearing.
Ninderry	Ninderry & Jensen Road	Cleared silt from culverts and pipes.
Noosaville	Noosa River	Outlets checked and cleared where necessary.
Noosaville	Cockell Shell & Gibson Road	Stormwater system checked and cleared.
Noosaville	Piper Street	Stormwater system checked and cleared.
Pomona	Reserve Street	Silt and debris removal at the stormwater inlet and outlet located at Rifle Street intersection.
Pomona	School Street	Table drain establishment near property number 23.
Pomona	Station Street	Debris cleared from the inlet and outlet at the railway floodway.
Pomona	Rifle Street	Table drain clearing.
Sunshine Beach	Seaview Terrace	Table drain establishment.
Sunshine Beach	Orient Drive	Reinstated road edge and relined concrete drain.
Tewantin	Golf Course Drive/McKinnon Drive	Survey of the receiving downstream natural channel (within Conservation land). To set tailwater level and determine if any high points exist.
Tewantin	Bungee Court	Open drain clearing (silt build up removal) including park area.
Tewantin	Golf Course Drive	Open drain cleared, including silt removal from Daintree Way culverts on west side of road.
Tewantin	Homestead Drive	Maintenance of large open drain.
Alexandra Heads	Janet Street	Pit replacement downstream of stormwater easement.
Alexandra Heads	Janet Street	Concept design for road and footpath modifications.
Alexandra Heads	Mary Street	Stormwater network within easement between George and Janet streets cleared of restrictions (root intrusion). Two field inlet pits installed, another two repaired.
Alexandra Heads	Juan Street	Footpath lowering to promote overland flow.

Flood Report Att 4 Actions

Buddina	Iluka Avenue	Unity Water service pipe conflict with stormwater network resolved.
Buddina	Various	Stormwater Quality Improvement Device (SQID)/in-pit basket maintenance for potential improvement to network capacity.
Buddina	Alkira Street	Reline of underground stormwater network as a result of multiple sink holes forming.
Maroochydore	School Road	Overland flow path establishment near child care facility.
Minyama	Mooloolah Drive	Underground pipe rehab for sink hole rectification.
Minyama	Various	SQID/in-pit basket maintenance for potential improvement to network capacity.
Mooloolaba	Coree Court	Pit upgrades as well as kerb and channel rehabilitation.
Mooloolaba	Ocean View Avenue	Overland flow path establishment near property number 40.
Mooloolaba	Careela Street/ Ocean View Avenue	Survey of drainage easement (overland flow) to ascertain whether the flow path is free from obstructions.
Mooloolaba	Careela Street/ Ocean View Avenue	CCTV of underground network and consultation with Unity Water to resolve service obstructions to the underground stormwater network (in progress).